

Instructions for HHI-CBK41

2-piece clamp bushing & screw Assy HHI Lower Triple Tree Pinch (sold each)

1. Apply a small amount of anti-seize to the clamp bushing outside diameter.
2. Apply blue Loctite to the screw threads.
3. Insert the 2-piece clamp bushing and screw assembly into the lower tree clamp hole leaving the screw loose.
4. Align the gap in the clamp bushing with the fork tube hole to allow the fork tube to pass through.
5. Secure tubes by tightening both clamp bushing screws to approximately 10ft-lbs.

